



## REGIONAL DISTRICT OF CENTRAL KOOTENAY

# Public Notice

February 5, 2020

## DENVER SIDING WATER USERS

Please be advised that the water main break has not yet been located. A valve has been throttled to limit leak outflow for maintaining system pressure and reservoir levels. There is currently adequate supply for indoor domestic use for users on the system.

Due to the high snow levels and no apparent surface water to indicate the location of the leak, the Regional District will resume efforts to repair the main in the spring. The attached map indicates the section of water main that is being managed for the water main leak. Locals are encouraged to report any evidence of pooling water in this area to the Regional District.

Please note that two fire hydrants have been taken out of service due to the throttled water main. The New Denver fire department offers fire protection coverage to the Denver Siding area and does not use these hydrants for fire protection.

We apologize for any inconvenience this may cause.

Please note that Denver Siding Water System remains on a **Boil Water Notice**.

If you have any questions regarding this notification please contact:

RDCK Water Services Department  
PH: 250-352-8192 / 1-800-268-7325  
Email: [watercontact@rdck.bc.ca](mailto:watercontact@rdck.bc.ca)




# Denver Siding

## Legend

- Civic Address
- Hydrants and Standpipes
  - Standpipe
  - Hydrant
- Valves
- Address Range
- Streams (Large Scale)
- Water Mainline
- Cadastral
- Lakes (Mid Scale)

## Notes

Affected water main



0 200.00 m 10cm 1 : 2,000.00

Date Plotted: 2/5/2020

This product is for informational purposes and may not have been prepared for, or be suitable for, legal, engineering, or surveying purposes. Users of this information should review or consult the primary data and information sources to ascertain the usability of the information.